



**FIG. 3** 





**FIG. 5** 






FIG. 6



**FIG. 7** 



**FIG. 8** 




FIG. 9





FIG. 10



Search Database	Add Routine	Delete Routine	<b>Exclude Routine</b>	LMOS Messages	Pending Search	Reports
ý	Ą.	D.	×	ij	ď	<u> </u>

LMOS TTN:Specify Sort Order? Dist:				1			, 					Work Code:	Type:	
LMOS TTN: Specify Sort O Dist:				To:	To:	To:	To:					IST:		. 1
PMA Number:  Status:  NPA WC:	Manager:	Supervisor:	Tech:	Work By: From:	Pending: From:	Dispatch: From:	Complete: From:	Work Address:	Work Description:	FST Narrative:	Disp Code:	Priority:	Auth #:	i

FIG. 13

	Ż	Order?							1	***			- <del>1</del>	ork Code:				
—— Search Criteria ——	Sort Order	PMA	NPA	Wire Center	District	Manager	Supervisor	Technician	Priority	Status	Authorization	Work By Date	Pending Date	Dispatch Date	Complete Date	TTN	Type	Work Address
	PMA Number:	Status:	NPA WC:	Manager:	Supervisor:	Work By: From:	Pending: From:	Dispatch: From:	Complete: From:	Work Address:	Work Description:	FST Narrative:	Disp Code:	Priority:	Cable:			

PM	1A Number	Auth	NPA	Wire Ctr	Dist Num	SI	PMA Number   Auth   NPA   Wire Ctr   Dist Num   S   Pending Date	Work By Date	Dispatch Date	Dispatch Date   Complete Date
99	990603181		404	283	1773	D	00/01/9	90/01/9	00/01/9	
66	990603322		404	283	1773		00/01/9	00/01/9	00/01/9	
66	990603187		404	284	1773		6/10/00	6/10/00	6/10/00	
66	990601004		404	285	1773	-	9/3/00	00/٤/9	00/8/9	
66	990603524		404	285	1773		6/10/00	90/01/9	6/10/00	
		Manager:	ger:	Smith		<b>(</b>	Supervisor:	Jones		
		Techi	ncian:	Technician: 999 999 999	660					
		IST:	DPO	IST:   DPO   Line Records:		404	404283RTAP01 LMOS TIN:	LMOS TTN:	1134	
		Pre-∕	Pre-Assign: Y		Priority: 5	1	Priority: 5   Estimated Time: 8	8:4	Actual Time:	
		Addit	ional 1	Fasks: N	Additional Tasks: N   Task: 1 of 1	1		# Cable Recs: 0		
		FST	Varrati	FST Narrative: ETA 0747A	47A					
		Work	Addre	ess: Main S	Work Address: Main Street Work Center	Cei	nter			
		Work	Desci	ription: Ru	n Helium or	ı Bı	ried Cable to I	Work Description: Run Helium on Buried Cable to Locate Air Leak		
••••										
ż	Notes, C	:- Cal	ble, M	- Messag	les, D -Dis	pat	ch, E - Edit, ;	N - Notes, C - Cable, M - Messages, D -Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit	rint, F - Find,	Q -Quit

FIG. 15

Complete Date			:					
Dispatch Date	6/10/00							
Work By Date	6/10/00							
PMA Number   Auth   NPA   Wire Ctr   Dist Num   S   Pending Date   Work By Date   Dispatch Date   Complete Date	1773 D Notes	Noice					9	
tr Dist Num S	1773							
NPA Wire C	707							
Number Auth	000502101							in the second
PM/	000				la la	1.	I	ļ

PMA Number   Auth   NPA   Wire Ctr   Dist Num   S   Pending Date   Work By Date   Dispatch Date   Complete Date	9/10/00 6/10/00	6/10/00 6/10/00	6/10/00 6/10/00	9/2/00 9/2/00	6/10/00			High Pair	1134	Actual Time:					
Pending Date V	9/10/00	6/10/00	6/10/00	9/3/00	:	PMA Cable Records		Low Pair	. 2	9/					
Dist Num S	1773 D	1773	1773	1773		PIMA Ca									20000000
Wire Ctr	283	283	284	285				Cable		7101					
h NPA	404	404	404	404	404		Manager:	Technician	IST: DPC	Pre-Assign	Additional	FST Narrat	Work Add	Work Des	J
Aut							Man	Tech	IST:	Pre-	Addi	FST	Wor	Wor	
PMA Number	990603181	990603322	990603187	990601004	990603524										

PMA Number Auth NPA Wire Ctr Dist Num S	Auth	NPA	Wire Ctr	Dist Num	S Pending Date	Work By Date	Dispatch Date	Complete Date
990603181		404	283	1773	D 6/10/00	6/10/00	6/10/00	
990603322		404	283	1773	6/10/00	6/10/00	6/10/00	
990603187		404	284	1773	6/10/00	6/10/00	6/10/00	
990601004		404	285	1773	90/8/9	9/3/00	9/3/00	
990603524		404	285	1773	W/10/VV	9/10/00	6/10/00	
					Other Message			

Created by: Smith


Dispatch Time: 0747 Complete Time: 1200

LMOS Return Message: 0055501 Created TN 205221RTPPS08

LMOS Time Stamp: 06/01/00 07:15:37 pckmcryk

			rint, F - Find, Q -Quit
FST Narrative: ETA 0747A	Work Address: Main Street Work Center	Work Description: Run Helium on Buried Cable to Locate Air Leak	N - Notes, C - Cable, M - Messages, D -Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit

FIG. 18



PMA Numbe	r Auth	NPA	Wire Ctr	Dist Num	PMA Number   Auth   NPA   Wire Ctr   Dist Num   S   Pending Date   Work By Date   Dispatch Date   Complete Date	Work By Date	Dispatch Date	Complete Date
990603181		404	283	1773	<u>00/01/9</u>	6/10/00	6/10/00	
990603322		404	<u>283</u>	<u>1773</u>	<u>6/10/00</u>	<u>6/10/00</u>	<u>6/10/00</u>	
990603187		404	284	1773	9/10/00	<u>00/01/9</u>	6/10/00	
990601004		404	285	1773	6/3/00	00/8/9	9/3/00	
990603524		404	285	<u>1773</u>	6/10/00	<u>6/10/00</u>	6/10/00	
	Mana	ager:	Manager: Smith		Supervisor:	Jones		
	Tech	niciar	Technician 999 999 999	660				
	IST:	DPO	IST:  DPO Line Records:		404283RTAP01 LMOS TIN:	LMOS TIN:	1134	
	Pre-⊿	Pre-Assign: Y	. Y	Priority: 5	Priority: 5   Estimated Time: 8	ie: 8	Actual Time:	
	Addit	ional	Fasks: N	Additional Tasks: N Task: 1 of 1		# Cable Recs: 0		
	FST	Narra	FST Narrative: ETA 0747A	0747A				
	Worl	k Addı	ress: Main	Work Address: Main Street Work Center	rk Center			
	Worl	k Desc	ription: F	Run Helium	Work Description: Run Helium on Buried Cable to Locate Air Leak	to Locate Air I	eak	
N - Notes,	C - Cal	ble, N	I - Messaç	jes, D -Dis <sub>l</sub>	N - Notes, C - Cable, M - Messages, D -Dispatch, E - Edit, S - Select, P - Print, F - Find, Q -Quit	S - Select, P - F	Print, F - Find,	Q -Quit

PMA Number	Auth	NPA	Wire Ctr	Dist Num	PMA Number   Auth   NPA   Wire Ctr   Dist Num   S   Pending Date   Work By Date   Dispatch Date   Complete Date	Work By Date	Dispatch Date	Complete Date
990603181		404	283	1773 D	D 6/10/00	6/10/00	6/10/00	
990603322		404	283	1773	00/01/9	٧/10/00	00/01/9	
990603187		404	100	Enter E-Ma	Enter E-Mail Recipient's Address	dress tage	00/0	
990601004		40					3/00	
990603524		40					00/0	
				8   	Valid User ID's			
	11	<u></u>	<b>~</b> I	Name		Phone	Supv	
	¥	Aainpal		CASH, JOHN	7	(555)-8268	NONE	
	Ö	Gdowmfu	•	JONES, GEORGE	RGE	(555)555-1234	34 NONE	
	¥	eppbyz		NELSON, WILL	ILL	(555)555-7890	90 ocziua	
	į	Jitbiqp		ROBBINS, MARTY	<b>MARTY</b>	(555)555-5561	61 mispnc	
	Z	htapql		WILLIAMS, H.	H.	(555)555-3456	56 Ipbyiv	
	P	Pmcxakl		WYNETTE, T.	T.	(555)555-3456		
				•				
N - Notes. C								-Quit
							,	

⋖
$\mathbf{H}$
≺
$\Box$
C
ž
$\equiv$
Þ
窗
畐
∢.
¥
ā

ADD

Dist #: Wire Center: NPA:

Maintenance Center: Type:

Mgr: Supv: Clear Data? Yes Priority: 5 Tech:

Pre-Assign:

IST:

Task: 1 of 1 Pre-Est:

Pending Date: Dispatch Date: Work By Date:

Work Code: Work Address: Work Desc:

Additional Tasks:

Auth:

e Status 05845339	Pending Date Dispatch Date Complete Date Type	01/00 RTAP
Delete Routine Status ——PMA Number: 005845339	Status Pending I	221 1111 P 06/01/00
I — PM	Dist	1111
	Wire Ctr	221
	NPA	205
	PMA Number NPA Wire Ctr Dist Status	005845339

Mgr: SMITH Tech: Presurvey Est: 6hr 0 min

Supv.: JONES
Pre-Assign: N Maintenance Ctr.: 900
Additional Tasks: N

Task: 1 of 1

Work Address: TEST Work Desc: TEST

1 record found. Delete? no

			NA	Exclude AA Num	Exclude Routine Status — PMA Number: 005845339	, 6		
PMA Number NPA Wire Ctr Dist	NPA	Wire Ctr	Dist	Status	Pending Date	Dispatch Date	Status Pending Date Dispatch Date Complete Date	Type
005845339	205	221	1111	Ь	205 221 1111 P 06/01/00			RTAP

Mgr: SMITH Tech:
Presurvey Est: 6hr 0 min

Supv: JONES
Pre-Assign: N Maintenance Ctr: 900
Additional Tasks: N

Task: 1 of 1

Work Address: TEST Work Desc: TEST

1 record found. Exclude? no

	LMOS Return Messages	
PMA Number	LMOS Time & Date	Complete Time & Date
000635924 0035226	06/01/00 06:15:00 created TTN 55555RTAP02	06/01/00 07:47:15
000655119 0059935	06/01/00 08:37:15 created TTN 55555RTAP13	06/01/00 11:56:43
000629881 0098662	06/02/00 14:22:56 created TTN 55555RTMISC11	06/03/00 09:33:40
P- Print, F- Find, Q- Quit	d, Q- Quit	

Search Criteria	Wire Ctr:  Dist #:  Mgr:  Supv:  Hour From:  Type:  Work Code:	

& 4 は X は B B B B B B B B B B B B B B B B B	Search Database Add Routine Delete Routine Exclude Routine LMOS Messages Pending Search	Reports	Address Summary Job Type Summary Time Summary Usage Summary Complete Summary Actual Time Summary Creator of Routine Ticket
1	% 4 G X 1 G	<b>ઝ</b>	4 ∺ ∺ Ω Ω ≽ × ≻

